FIG. 1




FIG. 2





FIG. 3






FIG. 5




FIG. 6





FIG. 7













FIG. 8B 74 75 72'



























FIG. 11







FIG. 14



URL http://	/www.maintain.co.jp/db/input.html
TROUBLE DB INPUT WINDOW	
OCCURRENCE DATE 2000/3/15 ~ 4040	
TYPE OF APPARATUS ******** ~ 4010	
SUBJECT OPERATING ERROR (START-UP ERROR) ~4030	
SERIAL NUMBER S/N 465NS4580001 ~ 4020	
DEGREE OF URGENCY D ~ 4050	
SYMPTOM	LED IS KEPT FLICKERING AFTER 位
	POWER-ON 4060
REMEDY	POWER ON AGAIN
	(PRESS RED BUTTON IN ACTIVATION) 4070
PROGRESS	INTERIM HAS BEEN DONE
	~4080
SEND (RESET) 4100 4110 4120	
LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE	

FIG. 16




FIG. 17

